

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
ORE,  
3-CAN,  
1-

Canby Railroad Depot  
Canby  
Clackamas County  
Oregon

HABS NO. OR-131

Documentation: 8 exterior photos (1980)  
3 interior photos (1980)  
2 data pages (1980)

B. Bergman, photographer October 3, 1980

- OR-131-1 GENERAL VIEW FROM NORTHWEST
- OR-131-2 GENERAL VIEW FROM NORTHEAST
- OR-131-3 SOUTHEAST ELEVATION
- OR-131-4 SOUTHWEST AND NORTHWEST ELEVATIONS
- OR-131-5 SOUTHEAST AND SOUTHWEST ELEVATIONS
- OR-131-6 NORTHEAST AND SOUTHEAST ELEVATIONS
- OR-131-7 NORTHWEST AND NORTHEAST ELEVATIONS
- OR-131-8 DETAIL OF WINDOW ON SOUTHEAST SIDE
- OR-131-9 GENERAL VIEW OF INTERIOR
- OR-131-10 WAITING AREA
- OR-131-11 WAREHOUSE END